



+ C21 needed only in case when pre-amp does not have capacitor in output. Otherwise bridge the C21.

All resistors +/-10%
Resistors 0,5W if not specified otherwise

REF.TO	PCB	MANAKOV AMP				PAGE	1/1
TUBE PWR AMP		SCALE	DES.BY	DR.BY	10.09.2006 EK		
FROM SU TV PARTS		CHECK	APPR				
TYPE	CIRCUIT DIAGRAM	DWG NR.		REV.	DATE	DR.BY	APPR